## Page 1 of 3

## Reconstruction Cost Estimate for: DALLAS CHANCEY

Prepared by: Tom TesterGA (44tt02fig) Valuation ID: A3T4-GG54.1 Cost per Finished Sq. Ft.: \$97.23

This is an estimate of reconstruction costs. We do not guarantee that this estimate reflects your home's actual reconstruction cost in the event of a loss.

#### **Owner Information**

Name: DALLAS CHANCEY Street: 1695 BRUSH CREEK DR City, State ZIP: MONROE, GA 30655 Country: USA Policy #: 997684192

#### **General Information**

Most Prevalent Number of Stories: **1 Story** Use: **Single Family Detached** Style: Unknown Cost per Finished Sq. Ft.: \$97.23

#### Foundation

Foundation Shape: 6-7 Corners - L Shape Foundation Material: 100% Brick

#### Exterior

Roof Shape: **Gable** Roof Construction: 100% Wood Framed Exterior Wall Construction: **100% Wood Framing** 

#### Interior

Average Wall Height: 8 Floor Coverings: 80% Carpet, 20% Sheet Vinyl Ceiling Finish: 100% Paint

#### Rooms

Kitchens: 1 Medium - (11'x10') Bedrooms: 1 Medium - (10'x10'), 1 Large - (14'x12'), 1 Extra Large - (16'x14') Dining Rooms: 1 Medium - (18'x12') Laundry Rooms: 1 Small - (7'x5') Nooks: 1 Medium - (10'x10') Walk-In Closets: 1 Medium - (10'x8')

#### **Room Details**

Kitchen (Above Grade Room): Quality Adjustment: **None** Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Range Hood, 1 Free Standing Range Bath (Above Grade Room): Quality Adjustment: **None** Type: **Full Bath** Fixtures: 1 Acrylic/Fiberglass Tub/Shower Surr. Bath (Above Grade Room): Quality Adjustment: **None** Type: **Full Bath** Fixtures: 1 Acrylic/Fiberglass Tub/Shower Surr.



Date Entered: 04/27/2016 Date Calculated: 04/27/2016 Created By: Tom TesterGA (44tt02fig) User: Emma Ginn (441120fig)

Sq. Feet: **1625** Year Built: **2000** Quality Grade: **Economy** Site Access: Average - No Unusual Constraints

Foundation Type: 100% Concrete Slab Property Slope: None (0 - 15 degrees)

Number of Dormers: 0 Roof Cover: **100% Composition - 3 Tab Shingle** Exterior Wall Finish: **100% Siding - Vinyl** 

Interior Wall Material: **100% Drywall** Interior Wall Finish: **100% Paint** 

Bathrooms: 2 Full Bath Living Areas: 1 Small - (14'x10'), 1 Large - (20'x14') Entry/Foyer: 1 Small - (8'x6') Hallways: 1 Large - (15'x6') Utility Rooms: 1 Medium - (10'x8')

Size: Medium Counters: 100% Plastic Laminate

Size: Medium Vanity Tops: 100% Plastic Laminate

Size: Medium Vanity Tops: 100% Plastic Laminate

## 360Value Replacement Cost Valuation A3T4-GG54.1

Page	2	of	3
i ugo	~	01	0

Souvalue Replacement Cost valuation AST4-GG54.1	Fage 2 01 5
Bedroom (Above Grade Room):	
Quality Adjustment: None	Size: Medium
Bedroom (Above Grade Room):	
Quality Adjustment: None	Size: Large
Bedroom (Above Grade Room):	
Quality Adjustment: None	Size: X-Large
Living Area (Above Grade Room):	
Quality Adjustment: None	Size: Small
Living Area (Above Grade Room):	
Quality Adjustment: None	Size: Large
Dining Room (Above Grade Room):	
Quality Adjustment: None	Size: Medium
Entry/Foyer (Above Grade Room):	
Quality Adjustment: None	Size: Small
Laundry Room (Above Grade Room):	
Quality Adjustment: None	Size: Small
Hallway (Above Grade Room):	
Quality Adjustment: None	Size: Large
Nook (Above Grade Room):	
Quality Adjustment: None	Size: Medium
Utility Room (Above Grade Room):	Qie e Madium
Quality Adjustment: None	Size: Medium
Walk-In Closet (Above Grade Room):	Sizo, Madium
Quality Adjustment: None	Size: Medium
Attached Structures	
Garage #1:	
# Cars: <b>2 Car (397 - 576 sq. ft.)</b>	Style: Attached / Built-In
Porch #1:	
Square Footage: 120	Material: Concrete Porch
Covered: 100%	Enclosed: 100%
Outdoor Fireplace: No	
Key Quality Details	
Kitchen Counters: Plastic Laminate	Jetted Tubs: 0
Walk-in Closets: 1	Decorative Beams: 0
Rooms with Crown Molding: 0	Ornate Staircases: 0
Rooms with Chair Rail: 0	Rooms with Cathedral/Vaulted Ceilings: 0
Rooms with Trayed/Coved Ceilings: 0	
Systems	
Heating: 1 Forced Air Heating System	Air Conditioning: 1 Central Air Conditioning
Specialty Systems: 1 Fire Sprinkler System	
Home Features	
Exterior Doors: 2 Exterior Doors, 1 Sliding Patio Door	Electrical Features: 1 Electrical Service Size - 200 amp
Windows	
13 Vinyl Horizontal Sliding Medium (12 - 23 SF)	

# **Estimated Reconstruction Cost**

Calculated Value:

\$158,000.00

We do not guarantee that the reconstruction cost estimate will reflect your home's actual reconstruction costs in the event of a loss. We hope our estimate helps you so you can determine the amount of coverage you need. However, even if all of the factors available in the estimating system are or are not utilized in reaching the estimate or if all information is or is not accurately input, the result will still be an estimate which you need to evaluate for adequacy. The most important consideration is that you feel you have enough protection to rebuild your home if it were completely destroyed. If you feel this estimate is not enough, then you should choose an amount of insurance which does match your estimate. If you have questions about construction costs in your area, please consult a contractor or an appraiser.

(Reconstruction cost includes all applicable permits, fees, overhead, profit, sales tax, and debris removal)

# Attention Farmers Agent: To apply this estimate to the policy you must select 360Value Refresh in Express or Update in Policy Center.

16.4.16 PL:GAATXV\_APR16