Page 1 of 3

Reconstruction Cost Estimate for: BOBSIE P COATES

Prepared by: Emma Ginn (441120fig) Valuation ID: A3U7-YK77.5 Cost per Finished Sq. Ft.: \$128.92

This is an estimate of reconstruction costs. We do not guarantee that this estimate reflects your home's actual reconstruction cost in the event of a loss.

Owner Information

Name: **BOBSIE P COATES** Street: **2683 MARCIA DR** City, State ZIP: **LAWRENCEVILLE, GA 30044** Country: USA Policy #: **997975110**

General Information

Most Prevalent Number of Stories: **Split Level** Use: Single Family Detached Style: Unknown Cost per Finished Sq. Ft.: \$128.92

Foundation

Foundation Shape: 6-7 Corners - L Shape Percent of lowest level that is finished: **0%** Property Slope: None (0 - 15 degrees)

Exterior

Roof Shape: Gable Roof Construction: 100% Wood Framed Exterior Wall Construction: 100% Wood Framing

Interior

Average Wall Height: 8 Floor Coverings: 80% Carpet, 20% Sheet Vinyl Ceiling Finish: 100% Paint

Rooms

Kitchens: **1 Small - (9'x6')** Bedrooms: 3 Medium - (10'x10') Dining Rooms: 1 Medium - (18'x12') Laundry Rooms: 1 Small - (7'x5'), 1 Medium - (10'x8') Nooks: 1 Medium - (10'x10') Walk-In Closets: 2 Medium - (10'x8')

Room Details

Kitchen (Above Grade Room): Quality Adjustment: None Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Range Hood, 1 Free Standing Range Cabinets: Peninsula Bar Bath (Above Grade Room): Quality Adjustment: None Type: Full Bath Fixtures: 1 Ceramic Tile Tub/Shower Surr. Bath (Above Grade Room): Quality Adjustment: None Type: Full Bath Fixtures: 1 Ceramic Tile Tub/Shower Surr.



Date Entered: 05/10/2016 Date Calculated: 05/18/2016 Created By: Emma Ginn (441120fig) User: Emma Ginn (441120fig)

Sq. Feet: 1722 Year Built: 1985 Quality Grade: **Economy** Site Access: Average - No Unusual Constraints

Foundation Type: **100% Basement** Foundation Material: 100% Concrete Walk-out Basement: **Yes**

Number of Dormers: 0 Roof Cover: 100% Composition - 3 Tab Shingle Exterior Wall Finish: 100% Siding - Cedar (Clapboard)

Interior Wall Material: 100% Drywall Interior Wall Finish: 100% Paint

Bathrooms: 2 Full Bath Living Areas: 1 Small - (14'x10'), 2 Large - (20'x14'), 1 Extra Large - (22'x16') Entry/Foyer: 1 Small - (8'x6') Hallways: 1 Large - (15'x6'), 1 Extra Large - (15'x8') Utility Rooms: 2 Medium - (10'x8')

Size: Small Counters: 100% Plastic Laminate

Size: Small Vanity Tops: 100% Plastic Laminate

Size: Small Vanity Tops: 100% Plastic Laminate

360Value Replacement Cost Valuation A3U7-YK77.5

Bedroom (Above Grade Room): Quality Adjustment: None	Size: Medium
Bedroom (Above Grade Room): Quality Adjustment: None Bedroom (Above Grade Room):	Size: Medium
Quality Adjustment: None Living Area (Above Grade Room):	Size: Medium
Quality Adjustment: None Living Area (Above Grade Room):	Size: Small
Quality Adjustment: None Living Area (Above Grade Room):	Size: Large
Quality Adjustment: None Living Area (Above Grade Room):	Size: Large
Quality Adjustment: None Dining Room (Above Grade Room):	Size: X-Large
Quality Adjustment: None Entry/Foyer (Above Grade Room):	Size: Medium
Quality Adjustment: None Laundry Room (Above Grade Room):	Size: Small
Quality Adjustment: None Laundry Room (Above Grade Room):	Size: Small
Quality Adjustment: None Hallway (Above Grade Room):	Size: Medium
Quality Adjustment: None Hallway (Above Grade Room):	Size: Large
Quality Adjustment: None Nook (Above Grade Room):	Size: X-Large Size: Medium
Quality Adjustment: None Utility Room (Above Grade Room): Quality Adjustment: None	Size: Medium
Utility Room (Above Grade Room): Quality Adjustment: None	Size: Medium
Walk-In Closet (Above Grade Room): Quality Adjustment: None	Size: Medium
Walk-In Closet (Above Grade Room): Quality Adjustment: None	Size: Medium

Attached Structures

Garage #1: # Cars: 2 Car (397 - 576 sq. ft.) Living Area above Garage: 100% Porch #1: Square Footage: 60 Covered: 100% Outdoor Fireplace: No Deck #1: Square Footage: 200 Covered: 0% Shape: Rectangle Levels: 1

Key Quality Details

Kitchen Counters: Plastic Laminate Walk-in Closets: 2 Rooms with Crown Molding: 0 Rooms with Chair Rail: 0 Rooms with Trayed/Coved Ceilings: 0

Systems

Heating: 1 Forced Air Heating System

Style: Attached / Built-In

Material: **Treated Decking Porch** Enclosed: 0%

Material: **Treated Deck** Enclosed: 0% Height: 3 Benches Length(ft): 0

Jetted Tubs: 0 Decorative Beams: 0 Ornate Staircases: 0 Rooms with Cathedral/Vaulted Ceilings: 0

Air Conditioning: 1 Central Air Conditioning

Home Features

Exterior Doors: 3 Exterior Doors, 1 Sliding Patio Door

Windows

24 Vinyl Horizontal Sliding Medium (12 - 23 SF)

Estimated Reconstruction Cost

Calculated Value:



We do not guarantee that the reconstruction cost estimate will reflect your home's actual reconstruction costs in the event of a loss. We hope our estimate helps you so you can determine the amount of coverage you need. However, even if all of the factors available in the estimating system are or are not utilized in reaching the estimate or if all information is or is not accurately input, the result will still be an estimate which you need to evaluate for adequacy. The most important consideration is that you feel you have enough protection to rebuild your home if it were completely destroyed. If you feel this estimate is not enough, then you should choose an amount of insurance which does match your estimate. If you have questions about construction costs in your area, please consult a contractor or an appraiser.

(Reconstruction cost includes all applicable permits, fees, overhead, profit, sales tax, and debris removal)

Attention Farmers Agent: To apply this estimate to the policy you must select 360Value Refresh in Express or Update in Policy Center.

16.4.16 PL:GAATXV_APR16