

## Reconstruction Cost Estimate for: **HILARY CROWE**

Prepared by: Tom TesterGA (44tt02fig)

Valuation ID: A2U3-WH15.6

Cost per Finished Sq. Ft.: \$87.82

*This is an estimate of reconstruction costs. We do not guarantee that this estimate reflects your home's actual reconstruction cost in the event of a loss.*



### Owner Information

Name: **HILARY CROWE**  
Street: **604 RENEE DR**  
City, State ZIP: **LOGANVILLE, GA 30052**  
Country: **USA**  
Policy #: **988859342**

Date Entered: 08/13/2015  
Date Calculated: 09/03/2015  
Created By: Tom TesterGA (44tt02fig)  
User: Emma Ginn (441120fig)

### General Information

Most Prevalent Number of Stories: **2 Stories**  
Use: **Single Family Detached**  
Style: Unknown  
Cost per Finished Sq. Ft.: \$87.82

Sq. Feet: **1560**  
Year Built: **1989**  
Quality Grade: **Standard**  
Site Access: Average - No Unusual Constraints

### Foundation

Foundation Shape: 6-7 Corners - L Shape  
Foundation Material: 100% Concrete

Foundation Type: 100% Concrete Slab  
Property Slope: None (0 - 15 degrees)

### Exterior

Roof Shape: **Gable**  
Roof Construction: 100% Wood Framed  
Exterior Wall Construction: **100% Wood Framing**

Number of Dormers: 0  
Roof Cover: **100% Composition - 3 Tab Shingle**  
Exterior Wall Finish: **100% Siding - Vinyl**

### Interior

Average Wall Height: 8  
Floor Coverings: 80% Carpet, 20% Sheet Vinyl  
Ceiling Finish: 100% Paint

Interior Wall Material: **100% Drywall**  
Interior Wall Finish: 100% Paint

### Rooms

Kitchens: 1 Medium - (11'x10')  
Bedrooms: 3 Medium - (10'x10')  
Dining Rooms: 1 Medium - (18'x12')  
Laundry Rooms: 1 Small - (7'x5')  
Nooks: 1 Medium - (10'x10')  
Walk-In Closets: 1 Medium - (10'x8')

Bathrooms: 2 Full Bath  
Living Areas: 1 Small - (14'x10'), 1 Large - (20'x14')  
Entry/Foyer: 1 Small - (8'x6')  
Hallways: 1 Large - (15'x6')  
Utility Rooms: 1 Medium - (10'x8')

### Room Details

Kitchen (Above Grade Room):

Quality Adjustment: **None**  
Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Range Hood, 1 Free Standing Range  
Cabinets: Peninsula Bar

Size: **Medium**  
Counters: 100% Plastic Laminate

Bath (Above Grade Room):

Quality Adjustment: None  
Type: **Full Bath**  
Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Size: Medium  
Vanity Tops: 100% Plastic Laminate

Bath (Above Grade Room):

Quality Adjustment: None  
Type: **Full Bath**  
Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Size: Medium  
Vanity Tops: 100% Plastic Laminate

Bedroom (Above Grade Room): Quality Adjustment: None	Size: Medium
Bedroom (Above Grade Room): Quality Adjustment: None	Size: Medium
Bedroom (Above Grade Room): Quality Adjustment: None	Size: Medium
Living Area (Above Grade Room): Quality Adjustment: None	Size: Small
Living Area (Above Grade Room): Quality Adjustment: None	Size: Large
Dining Room (Above Grade Room): Quality Adjustment: None	Size: Medium
Entry/Foyer (Above Grade Room): Quality Adjustment: None	Size: Small
Laundry Room (Above Grade Room): Quality Adjustment: None	Size: Small
Hallway (Above Grade Room): Quality Adjustment: None	Size: Large
Nook (Above Grade Room): Quality Adjustment: None	Size: Medium
Utility Room (Above Grade Room): Quality Adjustment: None	Size: Medium
Walk-In Closet (Above Grade Room): Quality Adjustment: None	Size: Medium

### Attached Structures

---

Porch #1: Square Footage: <b>120</b> Covered: <b>100%</b> Outdoor Fireplace: No	Material: <b>Concrete Porch</b> Enclosed: <b>100%</b>
Deck #1: Square Footage: <b>100</b> Covered: 0% Shape: Rectangle Levels: 1	Material: <b>Treated Deck</b> Enclosed: 0% Height: 3 Benches Length(ft): 0

### Key Quality Details

---

Kitchen Counters: Plastic Laminate	Jetted Tubs: 0
Walk-in Closets: 1	Decorative Beams: 0
Rooms with Crown Molding: 0	Ornate Staircases: 0
Rooms with Chair Rail: 0	Rooms with Cathedral/Vaulted Ceilings: 0
Rooms with Trayed/Coved Ceilings: 0	

### Systems

---

Heating: 1 Forced Air Heating System	Air Conditioning: 1 Central Air Conditioning
--------------------------------------	--

### Home Features

---

Exterior Doors: 2 Exterior Doors, 1 Sliding Patio Door	Electrical Features: 1 Electrical Service Size - 200 amp
--	--

### Windows

---

12 Vinyl Horizontal Sliding Medium (12 - 23 SF)

## Estimated Reconstruction Cost

---

Calculated Value:

**\$137,000.00**

We do not guarantee that the reconstruction cost estimate will reflect your home's actual reconstruction costs in the event of a loss. We hope our estimate helps you so you can determine the amount of coverage you need. However, even if all of the factors available in the estimating system are or are not utilized in reaching the estimate or if all information is or is not accurately input, the result will still be an estimate which you need to evaluate for adequacy. The most important consideration is that you feel you have enough protection to rebuild your home if it were completely destroyed. If you feel

this estimate is not enough, then you should choose an amount of insurance which does match your estimate. If you have questions about construction costs in your area, please consult a contractor or an appraiser.

(Reconstruction cost includes all applicable permits, fees, overhead, profit, sales tax, and debris removal)

**Attention Farmers Agent: To apply this estimate to the policy you must select 360Value Refresh in Express or Update in Policy Center.**

15.7.18 PL:GAATXV\_JUL15