Page 1 of 3

Reconstruction Cost Estimate for: MICKEY EMERSON

Prepared by: Zaheed Hussain (441120fig) Valuation ID: A3N1-LD33.2 Cost per Finished Sq. Ft.: \$157.12

This is an estimate of reconstruction costs. We do not guarantee that this estimate reflects your home's actual reconstruction cost in the event of a loss.

Owner Information

Name: MICKEY EMERSON Street: 4555 ATHA CIR City, State ZIP: LOGANVILLE, GA 30052 Country: USA Policy #: 325877346

General Information

Most Prevalent Number of Stories: 1 Story Use: Single Family Detached Style: Unknown Cost per Finished Sq. Ft.: \$157.12

Foundation

Foundation Shape: 6-7 Corners - L Shape Foundation Material: 100% Concrete

Exterior

Roof Shape: Hip Roof Construction: 100% Wood Framed Exterior Wall Construction: 100% Wood Framing

Interior

Average Wall Height: 8 Floor Coverings: 100% Wood - Unknown Type Ceiling Finish: 100% Paint

Rooms

Kitchens: 1 Medium - (11'x10') Bedrooms: 2 Medium - (10'x10'), 1 Large - (14'x12') Dining Rooms: 1 Medium - (18'x12') Laundry Rooms: 1 Small - (7'x5') Nooks: 1 Medium - (10'x10') Walk-In Closets: 1 Medium - (10'x8')

Room Details

Kitchen (Above Grade Room): Quality Adjustment: None Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Space Saver Microwave, 1 Built-in Range Cabinets: Peninsula Bar Bath (Above Grade Room): Quality Adjustment: None Type: Full Bath Fixtures: 1 Ceramic Tile Tub/Shower Surr. Bath (Above Grade Room): Quality Adjustment: None Type: Full Bath Fixtures: 1 Ceramic Tile Tub/Shower Surr.



Date Entered: 04/09/2019 Date Calculated: 04/09/2019 Created By: Zaheed Hussain (441120fig) User: Zaheed Hussain (441120fig)

Sq. Feet: 1292 Year Built: 1999 Quality Grade: Standard Site Access: Average - No Unusual Constraints

Foundation Type: 100% Concrete Slab Property Slope: None (0 - 15 degrees)

Number of Dormers: 0 Roof Cover: **100% Composition - 3 Tab Shingle** Exterior Wall Finish: **100% Siding - Vinyl**

Interior Wall Material: 100% Drywall Interior Wall Finish: 75% Paint, 25% Wallpaper

Bathrooms: 2 Full Bath Living Areas: 1 Large - (20'x14') Entry/Foyer: 1 Small - (8'x6') Hallways: 1 Medium - (15'x4') Utility Rooms: 1 Small - (7'x5')

Size: Medium Counters: 100% Plastic Laminate

Size: Medium Vanity Tops: 100% Plastic Laminate

Size: Medium Vanity Tops: 100% Plastic Laminate

360Value Replacement Cost Valuation A3N1-LD33.2

# Cars: 2 Car (397 - 576 sq. ft.)	Style: Attached / Built-In	
Garage #1:		
Attached Structures		
Quality Adjustment: None	Size: Medium	
Walk-In Closet (Above Grade Room):		
Quality Adjustment: None	Size: Small	
Utility Room (Above Grade Room):		
Quality Adjustment: None	Size: Medium	
Nook (Above Grade Room):		
Quality Adjustment: None	Size: Medium	
Hallway (Above Grade Room):		
Quality Adjustment: None	Size: Small	
Laundry Room (Above Grade Room):		
Quality Adjustment: None	Size: Small	
Entry/Foyer (Above Grade Room):		
Quality Adjustment: None	Size: Medium	
Dining Room (Above Grade Room):		
Room Features: Cathedral/Vaulted Ceiling	č	
Quality Adjustment: None	Size: Large	
Living Area (Above Grade Room):		
Quality Adjustment: None	Size: Large	
Bedroom (Above Grade Room):		
Quality Adjustment: None	Size: Medium	
Bedroom (Above Grade Room):		
Quality Adjustment: None	Size: Medium	
Bedroom (Above Grade Room):		

Porch #1: Square Footage: 144 Covered: 100% Outdoor Fireplace: No Patio #1: Square Footage: 100 Covered: 0% Outdoor Fireplace: No

Key Quality Details

Kitchen Counters: Plastic Laminate Walk-in Closets: 1 Rooms with Crown Molding: 0 Rooms with Chair Rail: 0 Rooms with Trayed/Coved Ceilings: 0

Systems

Heating: 1 Forced Air Heating System Fireplace #1: Type: Zero Clearance Fireplace

Home Features

Exterior Doors: 2 Exterior Doors, 1 Sliding Patio Door Lighting: 1 Ceiling Fan

Windows

10 Vinyl Horizontal Sliding Medium (12 - 23 SF)

Estimated Reconstruction Cost

Calculated Value:

\$203,000.00

We do not guarantee that the reconstruction cost estimate will reflect your home's actual reconstruction costs in the event of a loss. We hope our estimate helps you so you can determine the amount of coverage you need. However, even if all of the

Attached / Bulit-In

Material: Concrete Porch Enclosed: 25%

Material: Concrete Patio Enclosed: 0%

Jetted Tubs: 0 Decorative Beams: 0 Ornate Staircases: 0 Rooms with Cathedral/Vaulted Ceilings: 1 Zero Clearance Fireplace: 1

Air Conditioning: 1 Central Air Conditioning

Fireplace Details: 1 Mantel, 1 Brick Face

Electrical Features: 1 Electrical Service Size - 100 amp

factors available in the estimating system are or are not utilized in reaching the estimate or if all information is or is not accurately input, the result will still be an estimate which you need to evaluate for adequacy. The most important consideration is that you feel you have enough protection to rebuild your home if it were completely destroyed. If you feel this estimate is not enough, then you should choose an amount of insurance which does match your estimate. If you have questions about construction costs in your area, please consult a contractor or an appraiser.

(Reconstruction cost includes all applicable permits, fees, overhead, profit, sales tax, and debris removal)

Attention Farmers Agent: To apply this estimate to the policy you must select 360Value Refresh in Express or Update in Policy Center.

19.1.26 PL:GAATXV_JAN19