Page 1 of 3

Reconstruction Cost Estimate for: JORGE ESPINOSA

Prepared by: Zaheed Hussain (441120fig) Valuation ID: A4X3-FW89.2 Cost per Finished Sq. Ft.: \$61.49

This is an estimate of reconstruction costs. We do not guarantee that this estimate reflects your home's actual reconstruction cost in the event of a loss.

Owner Information

Name: JORGE ESPINOSA Street: 203 OVERLOOK PT City, State ZIP: DALLAS, GA 30157 Country: USA Policy #: 305854303

General Information

Most Prevalent Number of Stories: 1 Story Use: Single Family Detached Style: Unknown Cost per Finished Sq. Ft.: \$61.49

Foundation

Foundation Shape: 8-10 Corners - T,U,Z Shape Percent of lowest level that is finished: **100%** Foundation Material: 100% Concrete Walk-out Basement: **Yes**

Exterior

Roof Shape: Gable Roof Construction: 100% Wood Framed Exterior Wall Construction: 100% Wood Framing

Interior

Average Wall Height: 8 Floor Coverings: 80% Carpet, 20% Sheet Vinyl Ceiling Finish: 100% Paint

Rooms

Kitchens: 1 Large - (15'x11') Bedrooms: 4 Medium - (10'x10') Dining Rooms: 1 Medium - (18'x12') Laundry Rooms: 1 Medium - (10'x8') Nooks: 1 Medium - (10'x10') Walk-In Closets: 1 Large - (12'x10')

Room Details

Kitchen (Above Grade Room): Quality Adjustment: None Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Range Hood, 1 Free Standing Range Cabinets: Peninsula Bar Bath (Above Grade Room): Quality Adjustment: None Type: Full Bath Fixtures: 1 Ceramic Tile Tub/Shower Surr.



Date Entered: 04/24/2017 Date Calculated: 06/22/2017 Created By: Zaheed Hussain (441120fig) User: Zaheed Hussain (441120fig)

Sq. Feet: 2236 Year Built: 2007 Quality Grade: **Standard** Site Access: Average - No Unusual Constraints

Foundation Type: 100% Basement Basement Quality Adjustment: None Property Slope: None (0 - 15 degrees)

Number of Dormers: 0 Roof Cover: 100% Composition - 3 Tab Shingle Exterior Wall Finish: **75% Siding - Vinyl, 25% Brick Veneer**

Interior Wall Material: 100% Drywall Interior Wall Finish: 100% Paint

Bathrooms: **3 Full Bath** Living Areas: 1 Medium - (18'x12'), 1 Large - (20'x14') Entry/Foyer: 1 Medium - (10'x10') Hallways: 1 Medium - (15'x4'), 1 Large - (15'x6') Utility Rooms: 1 Large - (12'x10')

Size: Large Counters: 100% Plastic Laminate

Size: Medium Vanity Tops: 100% Plastic Laminate

360Value Replacement Cost Valuation A4X3-FW89.2

Bath (Above Grade Room):	
Quality Adjustment: None	Size: Medium
Type: Full Bath	Vanity Tops: 100% Plastic Laminate
Fixtures: 1 Ceramic Tile Tub/Shower Surr.	
Bath (Above Grade Room):	
Quality Adjustment: None	Size: Medium
Type: Full Bath	Vanity Tops: 100% Plastic Laminate
Fixtures: 1 Ceramic Tile Tub/Shower Surr.	
Bedroom (Above Grade Room):	
Quality Adjustment: None	Size: Medium
Bedroom (Above Grade Room):	
Quality Adjustment: None	Size: Medium
Bedroom (Above Grade Room):	
Quality Adjustment: None	Size: Medium
Bedroom (Above Grade Room):	
Quality Adjustment: None	Size: Medium
Living Area (Above Grade Room):	
Quality Adjustment: None	Size: Medium
Living Area (Above Grade Room):	
Quality Adjustment: None	Size: Large
Dining Room (Above Grade Room):	
Quality Adjustment: None	Size: Medium
Entry/Foyer (Above Grade Room):	
Quality Adjustment: None	Size: Medium
Laundry Room (Above Grade Room):	
Quality Adjustment: None	Size: Medium
Hallway (Above Grade Room):	
Quality Adjustment: None	Size: Medium
Hallway (Above Grade Room):	
Quality Adjustment: None	Size: Large
Nook (Above Grade Room):	
Quality Adjustment: None	Size: Medium
Utility Room (Above Grade Room):	
Quality Adjustment: None	Size: Large
Walk-In Closet (Above Grade Room):	-
Quality Adjustment: None	Size: Large
Attached Structures	
Attached Structures	

Α

Garage #1: # Cars: 2 Car (397 - 576 sq. ft.) Porch #1: Square Footage: 50 Covered: 0% Outdoor Fireplace: No Deck #1: Square Footage: 120 Covered: 0% Shape: Rectangle Levels: 1

Key Quality Details

Kitchen Counters: Plastic Laminate Walk-in Closets: 1 Rooms with Crown Molding: 0 Rooms with Chair Rail: 0 Rooms with Trayed/Coved Ceilings: 0

Systems

Heating: 1 Forced Air Heating System

Style: Attached / Built-In

Material: Concrete Porch Enclosed: 0%

Material: Treated Deck Enclosed: 0% Height: 3 Benches Length(ft): 0

Jetted Tubs: 0 Decorative Beams: 0 Ornate Staircases: 0 Rooms with Cathedral/Vaulted Ceilings: 0 Zero Clearance Fireplace: 1

Air Conditioning: 1 Central Air Conditioning

360Value Replacement Cost Valuation A4X3-FW89.2

Fireplace #1: Type: Zero Clearance Fireplace

Home Features

Exterior Doors: 3 Exterior Doors, 1 Sliding Patio Door

Windows

30 Vinyl Horizontal Sliding Medium (12 - 23 SF)

Estimated Reconstruction Cost

Calculated Value:

We do not guarantee that the reconstruction cost estimate will reflect your home's actual reconstruction costs in the event of a loss. We hope our estimate helps you so you can determine the amount of coverage you need. However, even if all of the factors available in the estimating system are or are not utilized in reaching the estimate or if all information is or is not accurately input, the result will still be an estimate which you need to evaluate for adequacy. The most important consideration is that you feel you have enough protection to rebuild your home if it were completely destroyed. If you feel this estimate is not enough, then you should choose an amount of insurance which does match your estimate. If you have questions about construction costs in your area, please consult a contractor or an appraiser.

(Reconstruction cost includes all applicable permits, fees, overhead, profit, sales tax, and debris removal)

Attention Farmers Agent: To apply this estimate to the policy you must select 360Value Refresh in Express or Update in Policy Center.

17.4.15 PL:GAROXV_APR17

Fireplace Details: 1 Mantel, 1 Brick Face

Electrical Features: 1 Electrical Service Size - 200 amp

Page 3 of 3

\$275,000.00