Page 1 of 3

Reconstruction Cost Estimate for: **JANE ESTES**

Prepared by: Barry Paul (449921fig) Valuation ID: A1K5-PQ11.7 Cost per Finished Sq. Ft.: \$121.97

This is an estimate of reconstruction costs. We do not guarantee that this estimate reflects your home's actual reconstruction cost in the event of a loss.

Owner Information

Name: JANE ESTES Street: 2480 PENNINGTON RD City, State ZIP: NEWBORN, GA 30056 Country: USA Policy #: 964455645

General Information

Most Prevalent Number of Stories: **1 Story** Use: **Single Family Detached** Style: Unknown Cost per Finished Sq. Ft.: \$121.97

Foundation

Foundation Shape: 6-7 Corners - L Shape Foundation Material: 100% Concrete Walk-out Basement: No

Exterior

Roof Shape: **Gable** Roof Construction: 100% Wood Framed Exterior Wall Construction: **100% Wood Framing**

Interior

Average Wall Height: 8 Floor Coverings: 80% Carpet, 20% Sheet Vinyl Ceiling Finish: 100% Paint

Rooms

Kitchens: **1 Medium - (11'x10')** Bedrooms: 2 Medium - (10'x10'), 1 Large - (14'x12') Dining Rooms: 1 Medium - (18'x12') Laundry Rooms: 1 Small - (7'x5') Nooks: 1 Medium - (10'x10') Walk-In Closets: 1 Medium - (10'x8')

Room Details

Kitchen (Above Grade Room): Quality Adjustment: **None** Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Range Hood, 1 Free Standing Range Cabinets: Peninsula Bar Bath (Above Grade Room): Quality Adjustment: None Type: **Full Bath** Fixtures: 1 Ceramic Tile Tub/Shower Surr. Bath (Above Grade Room): Quality Adjustment: None Type: **Full Bath** Fixtures: 1 Ceramic Tile Tub/Shower Surr.



Date Entered: 01/02/2013 Date Calculated: 02/12/2013 Created By: Barry Paul (449921fig) User: Zaheed Hussain (441120fig)

Sq. Feet: **1320** Year Built: **2007** Quality Grade: **Standard** Site Access: Average - No Unusual Constraints

Foundation Type: **100% Pier & Grade Beam** Property Slope: None (0 - 15 degrees)

Number of Dormers: 0 Roof Cover: **100% Composition - Architectural Shingle** Exterior Wall Finish: **100% Siding - Vinyl**

Interior Wall Material: 100% Drywall Interior Wall Finish: 100% Paint

Bathrooms: **2 Full Bath** Living Areas: 1 Large - (20'x14') Entry/Foyer: 1 Small - (8'x6') Hallways: 1 Medium - (15'x4') Utility Rooms: 1 Small - (7'x5')

Size: Medium Counters: 100% Plastic Laminate

Size: Medium Vanity Tops: 100% Plastic Laminate

Size: Medium Vanity Tops: 100% Plastic Laminate

360Value Replacement Cost Valuation A1K5-PQ11.7

Bedroom (Above Grade Room): Quality Adjustment: None	Size: Medium
Bedroom (Above Grade Room): Quality Adjustment: None	Size: Medium
Bedroom (Above Grade Room):	Sizo: Lorgo
Quality Adjustment: None Living Area (Above Grade Room):	Size: Large
Quality Adjustment: None	Size: Large
Dining Room (Above Grade Room): Quality Adjustment: None	Size: Medium
Entry/Foyer (Above Grade Room):	
Quality Adjustment: None Laundry Room (Above Grade Room):	Size: Small
Quality Adjustment: None	Size: Small
Hallway (Above Grade Room): Quality Adjustment: None	Size: Medium
Nook (Above Grade Room):	
Quality Adjustment: None Utility Room (Above Grade Room):	Size: Medium
Quality Adjustment: None	Size: Small
Walk-In Closet (Above Grade Room): Quality Adjustment: None	Size: Medium

Attached Structures

Garage #1: # Cars: 2 Car (397 - 576 sq. ft.) Porch #1: Square Footage: 80 Covered: 100% Outdoor Fireplace: No

Key Quality Details

Kitchen Counters: Plastic Laminate Walk-in Closets: 1 Rooms with Crown Molding: 0 Rooms with Chair Rail: 0 Rooms with Trayed/Coved Ceilings: 0

Systems

Heating: 1 Forced Air Heating System

Air Conditioning: 1 Central Air Conditioning

Rooms with Cathedral/Vaulted Ceilings: 0

Style: Attached / Built-In

Material: Concrete Porch

Enclosed: 0%

Jetted Tubs: 0

Decorative Beams: 0

Ornate Staircases: 0

Home Features

Exterior Doors: 2 Exterior Doors, 1 Sliding Patio Door

Electrical Features: 1 Electrical Service Size - 100 amp

Windows

10 Vinyl Horizontal Sliding Medium (12 - 23 SF)

Estimated Reconstruction Cost

Calculated Value:

\$161,000.00

We do not guarantee that the reconstruction cost estimate will reflect your home's actual reconstruction costs in the event of a loss. We hope our estimate helps you so you can determine the amount of coverage you need. However, even if all of the factors available in the estimating system are or are not utilized in reaching the estimate or if all information is or is not accurately input, the result will still be an estimate which you need to evaluate for adequacy. The most important consideration is that you feel you have enough protection to rebuild your home if it were completely destroyed. If you feel this estimate is not enough, then you should choose an amount of insurance which does match your estimate. If you have questions about construction costs in your area, please consult a contractor or an appraiser.

(Reconstruction cost includes all applicable permits, fees, overhead, profit, sales tax, and debris removal)

Attention Farmers Agent: To apply this estimate to the policy you must

select 360Value Refresh in Express or Update in Policy Center.

13.1.19 PL:GAATXV_JAN13