Page 1 of 2

Reconstruction Cost Estimate for: **BRENDA HALL**

Prepared by: Tom TesterGA (44tt02fig) Valuation ID: A3Q1-YL61.3 Cost per Finished Sq. Ft.: \$125.00

This is an estimate of reconstruction costs. We do not guarantee that this estimate reflects your home's actual reconstruction cost in the event of a loss.

Owner Information

Name: **BRENDA HALL** Street: **1030 STEPHEN ST** City, State ZIP: **GREENSBORO, GA 30642** Country: USA Policy #: **995054050**

General Information

Most Prevalent Number of Stories: **1 Story** Use: **Single Family Detached** Style: Unknown Cost per Finished Sq. Ft.: \$125.00

Foundation

Foundation Shape: 6-7 Corners - L Shape Foundation Material: 100% Brick Average Post Height (in feet): 8

Exterior

Roof Shape: **Gable** Roof Construction: 100% Wood Framed Exterior Wall Construction: **100% Wood Framing**

Interior

Average Wall Height: 8 Floor Coverings: 80% Carpet, 20% Sheet Vinyl Ceiling Finish: 100% Paint

Rooms

Kitchens: 1 Medium - (11'x10') Bedrooms: 2 Medium - (10'x10'), 1 Large - (14'x12') Dining Rooms: 1 Small - (14'x10') Nooks: 1 Small - (8'x6')

Room Details

Kitchen (Above Grade Room): Quality Adjustment: **None** Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Range Hood, 1 Free Standing Range Cabinets: Peninsula Bar Bath (Above Grade Room): Quality Adjustment: **None** Type: **Half Bath** Bath (Above Grade Room): Quality Adjustment: **None** Type: **Full Bath** Fixtures: 1 Ceramic Tile Tub/Shower Surr. Bedroom (Above Grade Room): Quality Adjustment: None



Date Entered: 03/29/2016 Date Calculated: 04/27/2016 Created By: Tom TesterGA (44tt02fig) User: Emma Ginn (441120fig)

Sq. Feet: **1080** Year Built: **1965** Quality Grade: **Standard** Site Access: Average - No Unusual Constraints

Foundation Type: **100% Stilts with Sweep Away Walls** Property Slope: None (0 - 15 degrees)

Number of Dormers: 0 Roof Cover: **100% Metal - Standing Seam** Exterior Wall Finish: **100% Siding - Hardboard/Masonite**

Interior Wall Material: **100% Drywall** Interior Wall Finish: **100% Paint**

Bathrooms: **1 Half Bath**, 1 Full Bath Living Areas: 1 Large - (20'x14') Hallways: 1 Small - (10'x3') Utility Rooms: 1 Small - (7'x5')

Size: Medium Counters: 100% Plastic Laminate

Size: Small Vanity Tops: 100% Plastic Laminate

Size: Medium Vanity Tops: 100% Plastic Laminate

Size: Medium

360Value Replacement Cost Valuation A3Q1-YL61.3		Page 2 of 2
Bedroom (Above Grade Room):		
Quality Adjustment: None	Size: Medium	
Bedroom (Above Grade Room):		
Quality Adjustment: None	Size: Large	
Living Area (Above Grade Room):		
Quality Adjustment: None	Size: Large	
Dining Room (Above Grade Room):		
Quality Adjustment: None	Size: Small	
Hallway (Above Grade Room):	Size: Small	
Quality Adjustment: None Nook (Above Grade Room):	Size. Small	
Quality Adjustment: None	Size: Small	
Utility Room (Above Grade Room):	Size. Sinali	
Quality Adjustment: None	Size: Small	
Attached Structures		
Porch #1:		
Square Footage: 50	Material: Concrete Porch	
Covered: 100%	Enclosed: 100%	
Outdoor Fireplace: No		
Key Quality Details		
Kitchen Counters: Plastic Laminate	Jetted Tubs: 0	
Walk-in Closets: 0	Decorative Beams: 0	
Rooms with Crown Molding: 0	Ornate Staircases: 0	
Rooms with Chair Rail: 0	Rooms with Cathedral/Vaulted Ceilings: 0	
Rooms with Trayed/Coved Ceilings: 0		
Systems		
Specialty Systems: 1 Fire Sprinkler System		
Home Features		
Exterior Doors: 2 Exterior Doors, 1 Sliding Patio Door	Electrical Features: 1 Electrical Service Size	- 100 amp
Windows		
9 Aluminum Horizontal Sliding Medium (12 - 23 SF)		
,		

Estimated Reconstruction Cost

Calculated Value:

\$135,000.00

We do not guarantee that the reconstruction cost estimate will reflect your home's actual reconstruction costs in the event of a loss. We hope our estimate helps you so you can determine the amount of coverage you need. However, even if all of the factors available in the estimating system are or are not utilized in reaching the estimate or if all information is or is not accurately input, the result will still be an estimate which you need to evaluate for adequacy. The most important consideration is that you feel you have enough protection to rebuild your home if it were completely destroyed. If you feel this estimate is not enough, then you should choose an amount of insurance which does match your estimate. If you have questions about construction costs in your area, please consult a contractor or an appraiser.

(Reconstruction cost includes all applicable permits, fees, overhead, profit, sales tax, and debris removal)

Attention Farmers Agent: To apply this estimate to the policy you must select 360Value Refresh in Express or Update in Policy Center.

16.4.16 PL:GAAHXV_APR16