Page 1 of 3

Reconstruction Cost Estimate for: TAIJPAUL DEODATH

Prepared by: Abdul Panjwani (441982fig) Valuation ID: A2Q6-ZU22.4 Cost per Finished Sq. Ft.: \$92.21

This is an estimate of reconstruction costs. We do not quarantee that this estimate reflects your home's actual reconstruction cost in the event of a loss.

Owner Information

Name: TAIJPAUL DEODATH Street: 937 SIMONTON VIEW LN City, State ZIP: LAWRENCEVILLE, GA 30045 Country: USA Policy #: 988095184

General Information

Most Prevalent Number of Stories: 2 Stories Use: Single Family Detached Style: Unknown Cost per Finished Sq. Ft.: \$92.21

Foundation

Foundation Shape: 13+ Corners - Irregular/Complex Foundation Material: 100% Concrete

Exterior

Roof Shape: Gable Roof Construction: 100% Wood Framed Exterior Wall Construction: 100% Wood Framing

Interior

Average Wall Height: 8 Floor Coverings: 80% Carpet, 20% Sheet Vinyl Ceiling Finish: 100% Paint

Rooms

Kitchens: 1 Large - (15'x11') Bedrooms: 4 Medium - (10'x10') Dining Rooms: 1 Large - (20'x14') Laundry Rooms: 1 Large - (12'x10') Nooks: 1 Large - (14'x12') Walk-In Closets: 1 Large - (12'x10'), 1 Extra Large -(15'x12')

Room Details

Kitchen (Above Grade Room):	
Quality Adjustment: None	Size: Large
Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Range	Counters: 100% Plastic
Hood, 1 Free Standing Range	
Cabinets: Peninsula Bar	
Bath (Above Grade Room):	
Quality Adjustment: None	Size: Medium
Type: Half Bath	Vanity Tops: 100% Plas
Bath (Above Grade Room):	
Quality Adjustment: None	Size: Medium
Type: Full Bath	Vanity Tops: 100% Plas
Fixtures: 1 Ceramic Tile Tub/Shower Surr.	



Date Entered: 06/23/2015 Date Calculated: 07/13/2015 Created By: Abdul Panjwani (441982fig) User: Emma Ginn (441120fig)

Sq. Feet: 3004 Year Built: 2004 Quality Grade: Standard Site Access: Average - No Unusual Constraints

Foundation Type: 100% Concrete Slab Property Slope: None (0 - 15 degrees)

Number of Dormers: 0 Roof Cover: 100% Composition - 3 Tab Shingle Exterior Wall Finish: 75% Siding - Cedar (Clapboard), 25% Brick Veneer

Interior Wall Material: 100% Drywall Interior Wall Finish: 100% Paint

Bathrooms: 1 Half Bath, 2 Full Bath Living Areas: 2 Extra Large - (22'x16') Entry/Foyer: 1 Medium - (10'x10'), 1 Large - (14'x12') Hallways: 2 Large - (15'x6') Utility Rooms: 2 Large - (12'x10') Pantries: 1 Medium - (10'x8')

Laminate

stic Laminate

stic Laminate

360Value Replacement Cost Valuation A2Q6-ZU22.4

Page	2	of	3
i ugo	~	U,	U

Bath (Above Grade Room): Quality Adjustment: None	Size: Medium
Type: Full Bath	Vanity Tops: 100% Plastic Laminate
Fixtures: 1 Ceramic Tile Tub/Shower Surr.	Vality 1003. 100701 lastic Earlinate
Bedroom (Above Grade Room):	
Quality Adjustment: None	Size: Medium
Bedroom (Above Grade Room):	
Quality Adjustment: None	Size: Medium
Bedroom (Above Grade Room):	
Quality Adjustment: None	Size: Medium
Bedroom (Above Grade Room):	
Quality Adjustment: None	Size: Medium
Living Area (Above Grade Room):	
Quality Adjustment: None	Size: X-Large
Living Area (Above Grade Room):	-
Quality Adjustment: None	Size: X-Large
Dining Room (Above Grade Room):	
Quality Adjustment: None	Size: Large
Entry/Foyer (Above Grade Room):	
Quality Adjustment: None	Size: Medium
Entry/Foyer (Above Grade Room):	
Quality Adjustment: None	Size: Large
Laundry Room (Above Grade Room):	
Quality Adjustment: None	Size: Large
Hallway (Above Grade Room):	
Quality Adjustment: None	Size: Large
Hallway (Above Grade Room):	
Quality Adjustment: None	Size: Large
Nook (Above Grade Room):	
Quality Adjustment: None Utility Room (Above Grade Room):	Size: Large
Quality Adjustment: None	Size: Large
Utility Room (Above Grade Room):	Size. Laige
Quality Adjustment: None	Size: Large
Walk-In Closet (Above Grade Room):	Olzo. Largo
Quality Adjustment: None	Size: Large
Walk-In Closet (Above Grade Room):	0.201 201 90
Quality Adjustment: None	Size: X-Large
Pantry (Above Grade Room):	
Quality Adjustment: None	Size: Medium

Attached Structures

Garage #1: # Cars: 2 Car (397 - 576 sq. ft.) Living Area above Garage: 0% Porch #1: Square Footage: 300 Covered: 100% Outdoor Fireplace: No Deck #1: Square Footage: 500 Covered: 0% Shape: Rectangle Levels: 1

Key Quality Details

Kitchen Counters: Plastic Laminate Walk-in Closets: 2 Rooms with Crown Molding: 0 Rooms with Chair Rail: 0 Style: Attached / Built-In

Material: Concrete Porch Enclosed: 0%

Material: Treated Deck Enclosed: 0% Height: 3 Benches Length(ft): 0

Jetted Tubs: 0 Decorative Beams: 0 Ornate Staircases: 0 Rooms with Cathedral/Vaulted Ceilings: 0

360Value Replacement Cost Valuation A2Q6-ZU22.4

Rooms with Trayed/Coved Ceilings: 0

Systems

Heating: 1 Forced Air Heating System Fireplace #1: Type: Zero Clearance Fireplace

Home Features

Exterior Doors: 3 Exterior Doors, 2 Sliding Patio Door Lighting: 1 Ceiling Fan

Windows

20 Vinyl Horizontal Sliding Medium (12 - 23 SF)

Estimated Reconstruction Cost

Calculated Value:

Zero Clearance Fireplace: 1

Air Conditioning: 1 Central Air Conditioning

Fireplace Details: 1 Mantel, 1 Brick Face

Electrical Features: 1 Electrical Service Size - 200 amp

\$277,000.00

We do not guarantee that the reconstruction cost estimate will reflect your home's actual reconstruction costs in the event of a loss. We hope our estimate helps you so you can determine the amount of coverage you need. However, even if all of the factors available in the estimating system are or are not utilized in reaching the estimate or if all information is or is not accurately input, the result will still be an estimate which you need to evaluate for adequacy. The most important consideration is that you feel you have enough protection to rebuild your home if it were completely destroyed. If you feel this estimate is not enough, then you should choose an amount of insurance which does match your estimate. If you have questions about construction costs in your area, please consult a contractor or an appraiser.

(Reconstruction cost includes all applicable permits, fees, overhead, profit, sales tax, and debris removal)

Attention Farmers Agent: To apply this estimate to the policy you must select 360Value Refresh in Express or Update in Policy Center.

15.4.18 PL:GAATXV_APR15