## **Reconstruction Cost Estimate for:** SHAILESH PRASAD

Prepared by: Matthew Hahn (96778cfig) Valuation ID: A6P2-IH28.2 Cost per Finished Sq. Ft.: \$256.24

This is an estimate of reconstruction costs. We do not quarantee that this estimate reflects your home's actual reconstruction cost in the event of a loss.

#### **Owner Information**

Name: SHAILESH PRASAD Street: 6036 HOLLYHURST WAY City, State ZIP: SACRAMENTO, CA 95823 Country: USA Policy #: 952381689

#### **General Information**

Most Prevalent Number of Stories: 1 Story Use: Single Family Detached Style: Unknown Cost per Finished Sq. Ft.: \$256.24

#### Foundation

Foundation Shape: 6-7 Corners - L Shape Foundation Material: 100% Concrete

#### Exterior

Roof Shape: Gable Roof Construction: 100% Wood Framed Exterior Wall Construction: 100% Wood Framing

#### Interior

Average Wall Height: 8 Floor Coverings: 20% Sheet Vinyl, 80% Hardwood - Plank Ceiling Finish: 100% Paint

#### Rooms

Kitchens: 1 Medium - (11'x10') Bedrooms: 3 Medium - (10'x10') Dining Rooms: 1 Small - (14'x10') Nooks: 1 Small - (8'x6')

#### **Room Details**

Kitchen (Above Ground Room): Quality Adjustment: None Size: Medium Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Range Hood, 1 Free Standing Range Cabinets: Peninsula Bar Bath (Above Ground Room): Quality Adjustment: None Size: Medium Type: Full Bath Fixtures: 1 Ceramic Tile Tub/Shower Surr. Bath (Above Ground Room): Quality Adjustment: None Size: Medium Type: Full Bath Fixtures: 1 Ceramic Tile Tub/Shower Surr. Bedroom (Above Ground Room): Quality Adjustment: None Size: Medium



Date Entered: 03/07/2022 Date Calculated: 03/07/2022 Created By: Matthew Hahn (96778cfig) User: Matthew Hahn (96778cfig)

Sq. Feet: 1081 Year Built: 1966 Home Quality Grade: Standard Site Access: Average - No Unusual Constraints

Foundation Type: 100% Crawlspace Property Slope: None (0 - 15 degrees)

Number of Dormers: 0 Roof Cover: 100% Composition - Architectural Shingle Exterior Wall Finish: 100% Stucco - Traditional Hard Coat

Interior Wall Material: 100% Drywall Interior Wall Finish: 100% Paint

Bathrooms: 2 Full Bath Living Areas: 1 Large - (20'x14') Hallways: 1 Small - (10'x3') Utility Rooms: 1 Small - (7'x5')

Counters: 100% Plastic Laminate

Vanity Tops: 100% Plastic Laminate

Vanity Tops: 100% Plastic Laminate

360Value Replacement Cost Valuation A6P2-IH28.2	Page 2 of 3
Bedroom (Above Ground Room):	
Quality Adjustment: None	Size: Medium
Bedroom (Above Ground Room): Quality Adjustment: None	Size: Medium
Living Area (Above Ground Room):	
Quality Adjustment: None	Size: Large
Dining Room (Above Ground Room):	Size: Small
Quality Adjustment: None Hallway (Above Ground Room):	Size: Small
Quality Adjustment: None	Size: Small
Nook (Above Ground Room):	
Quality Adjustment: None Utility Room (Above Ground Room):	Size: Small
Quality Adjustment: None	Size: Small
Attached Structures Garage #1:	
# Cars: 2 Car (397 - 576 sq. ft.)	Style: Attached / Built-In
Porch #1:	•
Square Footage: 50	Material: Concrete Porch
Covered: 100% Outdoor Fireplace: No	Enclosed: 0%
Key Quality Details	
Kitchen Counters: Plastic Laminate Walk-in Closets: 0	Jetted Tubs: 0 Decorative Beams: 0
Rooms with Crown Molding: 0	Ornate Staircases: 0
Rooms with Chair Rail: 0	Rooms with Cathedral/Vaulted Ceilings: 0
Rooms with Trayed/Coved Ceilings: 0	
Systems	
Heating: 1 Forced Air Heating System	Air Conditioning: 1 Central Air Conditioning
Home Features	
Exterior Doors: 2 Exterior Doors, 1 Sliding Patio Door	Electrical Features: 1 Electrical Service Size - 100 amp
Windows           9 Aluminum Horizontal Sliding Medium (12 - 23 SF)	
Estimated Cost Breakdown	
Labor, Materials and Supplies: \$194,957.10	Demolition and Debris Removal: \$7,215.76
Architect Fees and Permits: \$20,943.13 Overhead and Profit: \$46,205.63	Other Fees and Taxes: \$7,912.17

### **Estimated Reconstruction Cost**

#### Calculated Value:

We do not guarantee that the reconstruction cost estimate will reflect your home's actual reconstruction costs in the event of a loss. We hope our estimate helps you so you can determine the amount of coverage you need. However, even if all of the factors available in the estimating system are or are not utilized in reaching the estimate or if all information is or is not accurately input, the result will still be an estimate which you need to evaluate for adequacy. The most important consideration is that you feel you have enough protection to rebuild your home if it were completely destroyed. If you feel this estimate is not enough, then you should choose an amount of insurance which does match your estimate. If you have questions about construction costs in your area, please consult a contractor or an appraiser.

(Reconstruction cost includes all applicable permits, fees, overhead, profit, sales tax, and debris removal)

# Attention Farmers Agent: To apply this estimate to the policy you must select 360Value Refresh in Express or Update in Policy Center.

21.10.9 PL:CASAXV\_MAR22

# \$277,000.00