### **Reconstruction Cost Estimate for:**

# **Bonita Davis**

Prepared by: Emma Ginn (441120fig)

Valuation ID: A4G9-FL14.1 Cost per Finished Sq. Ft.: \$99.22

This is an estimate of reconstruction costs. We do not quarantee that this estimate reflects your home's actual

reconstruction cost in the event of a loss.



#### **Owner Information**

Name: Bonita Davis Street: 550 AMISH AVE

City, State ZIP: RIVERDALE, GA 30296

Country: USA Policy #: 302525287 Date Entered: 09/14/2016 Date Calculated: 09/14/2016

Created By: Emma Ginn (441120fig) User: Emma Ginn (441120fig)

#### **General Information**

Most Prevalent Number of Stories: 2 Stories

Use: Single Family Detached

Style: Unknown

Cost per Finished Sq. Ft.: \$99.22

Sq. Feet: 1935 Year Built: 2006

Quality Grade: Standard

Site Access: Average - No Unusual Constraints

#### **Foundation**

Foundation Shape: 6-7 Corners - L Shape

Foundation Material: 100% Concrete

Foundation Type: 100% Concrete Slab

Property Slope: None (0 - 15 degrees)

#### Exterior

Roof Shape: Gable

Roof Construction: 100% Wood Framed

Exterior Wall Construction: 100% Wood Framing

Number of Dormers: 0

Roof Cover: 100% Composition - 3 Tab Shingle

Exterior Wall Finish: 100% Siding - Vinyl

#### Interior

Average Wall Height: 8

Floor Coverings: 80% Carpet, 20% Sheet Vinyl

Ceiling Finish: 100% Paint

Interior Wall Material: 100% Drywall Interior Wall Finish: 100% Paint

#### **Rooms**

Kitchens: 1 Medium - (11'x10')

Bedrooms: 4 Medium - (10'x10') Dining Rooms: 1 Small - (14'x10') Laundry Rooms: 1 Small - (7'x5')

Walk-In Closets: 1 Medium - (10'x8')

Bathrooms: 1 Half Bath, 2 Full Bath Living Areas: 1 Medium - (18'x12')

Entry/Foyer: 1 Small - (8'x6') Hallways: 1 Medium - (15'x4')

#### **Room Details**

Kitchen (Above Grade Room):

Quality Adjustment: None

Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Range

Hood, 1 Free Standing Range Cabinets: Peninsula Bar

Bath (Above Grade Room):

Quality Adjustment: None

Type: Half Bath

Bath (Above Grade Room):

Quality Adjustment: None

Type: Full Bath

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Size: Medium

Counters: 100% Plastic Laminate

Size: Small

Vanity Tops: 100% Plastic Laminate

Size: Medium

Vanity Tops: 100% Plastic Laminate

Bath (Above Grade Room):

Quality Adjustment: None Size: Medium

Type: Full Bath Vanity Tops: 100% Plastic Laminate

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bedroom (Above Grade Room):

Quality Adjustment: None Size: Medium

Bedroom (Above Grade Room):

Quality Adjustment: None Size: Medium

Bedroom (Above Grade Room):

Quality Adjustment: None Size: Medium

Bedroom (Above Grade Room):

Quality Adjustment: None Size: Medium

Living Area (Above Grade Room):

Quality Adjustment: None Size: Medium

Dining Room (Above Grade Room):

Quality Adjustment: None Size: Small

Entry/Foyer (Above Grade Room):

Quality Adjustment: None Size: Small

Laundry Room (Above Grade Room):

Quality Adjustment: None Size: Small

Hallway (Above Grade Room):

Quality Adjustment: None Size: Medium

Walk-In Closet (Above Grade Room):

Quality Adjustment: None Size: Medium

#### **Attached Structures**

Garage #1:

# Cars: 2 Car (397 - 576 sq. ft.) Style: Attached / Built-In

Living Area above Garage: 0%

Porch #1:

Square Footage: 120 Material: Concrete Porch

Covered: 100% Enclosed: 0%

Outdoor Fireplace: No

#### **Key Quality Details**

Kitchen Counters: Plastic Laminate Jetted Tubs: 0

Walk-in Closets: 1 Decorative Beams: 0
Rooms with Crown Molding: 0 Ornate Staircases: 0

Rooms with Chair Rail: 0 Rooms with Cathedral/Vaulted Ceilings: 0

Rooms with Trayed/Coved Ceilings: 0 Zero Clearance Fireplace: 1

**Systems** 

Heating: 1 Forced Air Heating System

Air Conditioning: 1 Central Air Conditioning

Fireplace #1:

Type: **Zero Clearance Fireplace** Fireplace Details: 1 Mantel, 1 Brick Face

**Home Features** 

Exterior Doors: 3 Exterior Doors, 1 Sliding Patio Door Electrical Features: 1 Electrical Service Size - 200 amp

#### Windows

15 Vinyl Horizontal Sliding Medium (12 - 23 SF)

## **Estimated Reconstruction Cost**

Calculated Value:

\$192,000.00

We do not guarantee that the reconstruction cost estimate will reflect your home's actual reconstruction costs in the event of a loss. We hope our estimate helps you so you can determine the amount of coverage you need. However, even if all of the factors available in the estimating system are or are not utilized in reaching the estimate or if all information is or is not accurately input, the result will still be an estimate which you need to evaluate for adequacy. The most important consideration is that you feel you have enough protection to rebuild your home if it were completely destroyed. If you feel

this estimate is not enough, then you should choose an amount of insurance which does match your estimate. If you have questions about construction costs in your area, please consult a contractor or an appraiser.

(Reconstruction cost includes all applicable permits, fees, overhead, profit, sales tax, and debris removal)

# Attention Farmers Agent: To apply this estimate to the policy you must select 360Value Refresh in Express or Update in Policy Center.

16.7.16 PL:GAATXV\_JUL16