

State Farm

BROWN, GLENDA FAYE

33-8651-H70

0.00 SF Walls	0.00 SF Ceiling	0.00 SF Walls & Ceiling
0.00 SF Floor	0.00 SF Short Wall	0.00 LF Floor Perimeter
0.00 SF Long Wall		0.00 LF Ceil. Perimeter

QUANTITY	UNIT PRICE	TAX	RCV	AGE/LIFE CONDITION	DEPREC. DEP %	ACV
No damage from a direct physical loss was found to this elevation.						
Totals: Right Elevation		0.00	0.00		0.00	0.00

Rear Elevation

0.00 SF Walls	0.00 SF Ceiling	0.00 SF Walls & Ceiling
0.00 SF Floor	0.00 SF Short Wall	0.00 LF Floor Perimeter
0.00 SF Long Wall		0.00 LF Ceil. Perimeter

QUANTITY	UNIT PRICE	TAX	RCV	AGE/LIFE CONDITION	DEPREC. DEP %	ACV
16. R&R Window screen, 10 - 16 SF						
1.00 EA	52.05	3.08	55.13	17/30 yrs Avg.	(31.24) 56.67%	23.89
17. Comb and straighten a/c condenser fins - w/out trip charge						
1.00 EA	67.52	0.00	67.52			67.52
to comb the AC fins on the window unit.						
Totals: Rear Elevation		3.08	122.65		31.24	91.41

Left Elevation

0.00 SF Walls	0.00 SF Ceiling	0.00 SF Walls & Ceiling
0.00 SF Floor	0.00 SF Short Wall	0.00 LF Floor Perimeter
0.00 SF Long Wall		0.00 LF Ceil. Perimeter

QUANTITY	UNIT PRICE	TAX	RCV	AGE/LIFE CONDITION	DEPREC. DEP %	ACV
No damage from a direct physical loss was found to this elevation.						
Totals: Left Elevation		0.00	0.00		0.00	0.00

Debris Removal

0.00 SF Walls	0.00 SF Ceiling	0.00 SF Walls & Ceiling
0.00 SF Floor	0.00 SF Short Wall	0.00 LF Floor Perimeter
0.00 SF Long Wall		0.00 LF Ceil. Perimeter