

09/01/2022

REBECCA MARR 267 MEADOWOOD LN VADNAIS HEIGHTS MN 55127 UNITED STATES

 Claim Number
 : 18390225

 Date of Loss
 : 05/06/2022

 Balance Due
 : \$1,205.22

Renter's name : REBECCA MARR

Billing Invoice : 3006543977 Rental Agreement# : 6914RW

We have submitted our claim to your insurance and / or credit card company. For your convenience, enclosed are copies of the information submitted.

We will make every effort to resolve the claim with your insurance and / or credit card company but please be advised that you are still responsible for any unpaid amounts.

Your policy may require you to pay a deductible. If you have not paid your deductible already please remit payment immediately to the address above. Please include our claim number on your payment. If you prefer you may also pay the amount due using a debit card, credit card or directly from your bank account at:

http://www.claimtopay.com

If you have any questions, please contact us at the number below.

Sincerely,

DAMAGE RECOVERY UNIT Phone: 8663004407 Email: DRU3@ehi.com

INVOICE

Date: 09/01/2022

REBECCA MARR
Claim #: 18390225
267 MEADOWOOD LN
Unit #: 7T3K0J

Unit #: 7T3K0J Billing Invoice #: 3006543977

VADNAIS HEIGHTS MN 55127 UNITED STATES

Vehicle Information

VIN: 2C4RC1GG6LR283618

Year: 2020 Make: CHRY Model: PACI

Item	Total Cost	Amount Due
Damage	\$928.02	\$928.02
Admin Fees	\$100.00	\$100.00
Loss of Use:	\$84.40	\$84.40
Diminishment of Value	\$92.80	\$92.80

Total Amount Due: \$ 1,205.22*

*Remit payment in U.S. Dollars.

Claim #: 18390225

Billing Invoice #: 3006543977

Unit #: 7T3K0J

PAY UPON RECEIPT

ALL PAYMENTS MUST INCLUDE THIS REMITTANCE TO BE CREDITED PROPERLY!

PAYABLE TO: DAMAGE RECOVERY P O BOX 801988 KANSAS CITY MO 64180 UNITED STATES Toll Free #: 8663004407

Total Amount Due: \$	1,205.22*
*Remit payment in U.S. Dollars.	

Total Amount Remitted: \$ _____

Estimate Information

Estimate ID 3014164794 Claim: 18390225

Engine:

Estimator:

File ID: 3332045044 Platform: CCC Date Created: 08/23/2022 Repair Facility

Repair Facility: Caliber Collision - Minnesota -

Fleet

Address: 2905 Lexington Ave. S

Prod. Date:

Eagan, MN 55121 Phone: 651-6914140

Fax: 651-6914154 Federal Tax ID: 33-0730794

State Tax ID: BAR:

Vehicle Data

Unit #: 7T3K0J Year: 2020 Make: Chrysler Model: Pacifica Limited

Odometer: 64424

FWD

VIN: 2C4RC1GG6LR283618 Color: Black - WBL Lic. State: NE License: WPP562

Point of Impact

Body Style: 4D VAN

Primary: Left Rear Side

Secondary: Unknown Point of Impact

Line									
Line	Op	Description	Type	Part#	Price	Qty	Labor	Paint	Labor Amt
001*	BLANK	PreScan					0B		
002*	BLANK	OE Diagnostic Post Scan			\$100.00		0.5B		\$23.60
003		ROOF							
004	RI	LT Roof rack					0.6B		\$28.32
005	RI	LT Roof molding rear					0.2B		\$9.44
006		PILLARS, ROCKER & FLOOR							
007*	RI	LT Rocker molding - Loosen					0.5B		\$23.60
008		SIDE PANEL							
009	RI	LT Wheelhouse liner					0.4B		\$18.88
010	RI	LT Applique panel					0.2B		\$9.44
011*	RI	LT Window molding chrome					0.3B		\$14.16
012*	RPR	LT Side panel					4.5B	2.7R	\$339.84
013	BLANK	Add for Clear Coat						1.1R	\$51.92
014	BLND	Fuel door						0.3R	\$14.16
015*	BLANK	Cover Car for Overspray			\$5.00		0.3B		\$14.16
016	RR	Corrosion Protection Primer						0.3R	\$14.16
017*	SUB	Hazardous Waste Disposal			\$7.50		0B		
018*	RR	Cavity Wax			\$10.00		0.5B		\$23.60
019*	BLANK	Rope Glass			\$6.00		0.5B		\$23.60
020	REF	Color Tint						0.5R	\$23.60
021		REAR LAMPS							
022	RI	LT Tail lamp quarter panel mounted w/o L					0.3B		\$14.16

Т	ota	ls

Parts				
Part	SubTotal	Adj%	Adj\$	Total
				\$0.00
Labor				
Type	Additional Labor	Rate	Hours	Total
Labor - Body		\$47.20	8.8	\$415.36
Labor - Refinish		\$47.20	4.9	\$231.28
Labors Total				\$646.64
Materials				
Materials - 2 Stage Pair	nt Materials			\$34.32
Materials - Blend				\$9.36
Materials - Paint				\$109.20
				\$152.88

Other - Sublet	\$7.50
Other - Additional Cost	\$121.00
	\$121.00
Adjustment	
Total Claim Before Taxes	\$928.02
Total Transaction Amount	\$928.02
Total Transaction Amount Insurance Pay	\$928.02 \$928.02

Op Codes				
RREP	Operation - Remove and Repair			
R1ST	Operation - Repair First, else Replace			
REDO	Operation - Redo			
CG	Operation - Chip Guard			
TT	Operation - Two Tone			
PDR	Operation - Paintless Dent Repair			
RPR	Operation - Repair			
PRPR	Operation - Repair, Partial			
RR	Operation - Remove/Replace			
RRP	Operation - Remove/Replace, Partial			
ADC	Operation - Additional Costs			
ADO	Operation - Additional Operations			
BLND	Operation - Blend			
SUB	Operation - Sublet			
RPD	Operation - Related Prior Damage			
AA	Operation - Appearance Allowance			
BLANK	Operation - Blank			
RFRP	Operation - Refinish/Repair			
RI	Operation - Remove/Install			
ARP	Operation - Additional Repair			
ALGN	Operation - Alignment			
O/H	Operation - Overhaul			
REF	Operation - Refinish			
INSP	Operation - Inspect			
C/AJ	Operation - Check/Adjust			
UPD	Operation - Unrelated Prior Damage			
RI	Operation - Remove and Reinstall			
	Part Type Codes			
A	Parts - Aftermarket			
C	Parts - Re-chromed			
Е	Parts - Existing			
L	Parts - Recycled			
M	Parts - Remanufactured			
N	Parts - New			
P	Parts - New, partial			
R	Parts - Re-cored			
GL	Glass			
Labor Codes				
R	Labor - Refinish			
S	Labor - Structural			
U	User Defined Labor			
U	User Defined Labor 1			
U	User Defined Labor 2			
U	User Defined Labor 3			
U	User Defined Labor 4			
В	Labor - Body			
D	Labor - Diagnostic			
	- E			
E	Labor - Electrical			

G	Labor - Glass	
M	Labor - Mechanical	











